



BHAVAN NIRMAN

ARCHITECTS, ENGINEERS & VALUERS

Krishnakant A. Pandat

(B.Arch., B.E. CIVIL, AIIA, FIIV, MCE, FEIO, FICCI)

Govt. Approved Valuer (Under Wealth tax 34AB Approved)

LCM - 2443, CAT-I - Immovable Properties, LCM - 2443, CAT-II - Agri. Lands

LCM - 2445, CAT-VII - Plant & Machinery

Registered Engineer - Structural Designer of Nagar Palika

*** Daulat Press Main Road, Bhavan Nirman, Near Railway Station, Opp. Fire Brigade, Veraval-362265.
*** Email - bhavannirmandoc1@gmail.com

REF.

DATE: 04/01/2020

REF. BNAE/VRL/STABILITY CERTIFICATE/TWSEIMC/4087

CERTIFICATE OF STABILITY & SAFETY OF EXISTING STRUCTURE

To whom so ever it may concern: -

Reference: - Name of Building:

"SHISHU MANDIR SCHOOL OF
EXCELLENCE" OF MOUJE VILLAGE
DARI, TA. VERAVAL, DIST. GIR -
SOMNATH.

This is to certify that I undersigned is possessing current registration to act as Structural designer/structural engineer vide structural engineer license Regd. No. GUDA/SD II/65/01/2012 of Gandhinagar urban development authority / Gandhinagar.

That I am fully conversant of my duties and responsibilities under the general Development control regulations, building bye laws, rules - provisions of the act in force, Indian standard codes, national building code etc.

That I have inspected the collage building aforesaid and checked all structural drawings And also inspected the construction standing at the site and have verified details Pertaining to the existing structure.

I, hereby, certify on the basis of my full inspection and investigation that existing Structure is safe and secure from every angle of safety and is constructed according to the Safety norms incorporated in the GDCR, bye laws, rules, provisions Of the act in force, is Code 1983 and other is code national building code etc.

Date: - 04/01/2020

Place: - Veraval

Dskadi
Mrs. Nasim S. Kadri
Principal

Shishumandir International
School-Dari, Veraval

Krishnakant A. Pandat

(Cha. Architect, Engineer & Govt. Regd. Valuer)

Govt. approved immovable property valuer, cat- I

KRISHNAKANT A. PANDAT

B. Arch. A. I. I. A.,

Architect & Govt. Regd. Valuer

Regd. No. CA/88/11826

VERAVAL, 362265



BHAVAN NIRMAN
ARCHITECTS, ENGINEERS & VALUERS

Krishnakant A. Pandat

(B. Arch. B. E. Civil, AIIA, FIIV, MCE, FEIO, FICCI)

Govt. Approved Valuer (Under Wealth tax 34AB Approved)
LCM - 2443, CAT-I - Immovable Properties, LCM - 2443, CAT-II - Agri. Lands,
LCM - 2445, CAT-VII - Plant & Machinery
Registered Engineer - Structural Designer of Nagar Palika

222 Daulat Press Main Road, Bhavan Nirman, Near Railway Station, Opp. Fire Brigade, Veraval-362265.
222 Email - bhavannirmandoc1@gmail.com

REF.

DATE 04/01/2020

REF. BNAE/VRL/BUC/TWSEIMC/4086

BUILDING USE CERTIFICATE

TO WHOM SO EVER IT MAY CONCERN:-

This is to certify that the school Bldg. of "SHISHU MANDIR SCHOOL OF EXCELLENCE" The school bldg. is located at village Dari, Ta. Veraval, Dist. Gir - Somnath. Which is handling by "SHRI SHISHU MANDIR EDUCATION TRUST - VERAVAL, TA. VERAVAL, DIST. GIR - SOMNATH". The school bldg. has been visited by me on dated 03/01/2020 & I found the following points about the structure of the School Bldg. as follows.

Owner:- "SHRI SHISHU MANDIR EDUCATION TRUST - VERAVAL.

- | | | |
|-----------------------|-----|--|
| Foundation | : - | 2'6" wide & up to depth of hard strata, filled with UCR. |
| Plinth | : - | From UCR masonry with C.C. Coping. |
| Super structure | : - | 0.23 Mts. Thick W.S. Bella fitted with cement - sand Slurry. |
| RCC Works | : - | Lintels, Chhajjas & Roof from RCC works of nece. Size & Thickness. |
| Finishing | : - | Cement plaster inside & outside. |
| Flooring | : - | From mosaic tiles. |
| Other features | : - | Doors & windows from non - teak wood, iron grills, color Coating inside & outside. |
| Light & ventilation:- | | The adequate light & ventilation provided, Hygienic condition for school living and educating. |
| Height | : - | 10'00 height of the floor i.e. from floor level to slab level 10'00 height. |

Report about the stability of the school Bldg.:-

I found no cracks, Brakes & other const. Defects anywhere in the collage Bldg. it is found safe & sound from all the ways. It is stand in good & stable position. There are no chances of Bldg. fallen down or collapse at any simple natural Circumstances.

Conclusion:-

The collage Bldg. Found safe & sound. No cracks, Brakes & other defects Found in the Bldg. can remain stable for years in simple natural circumstances.

The collage bldg. is structurally stable at my opinion

Date:- 04/01/2020

Place:- Veraval

Mrs. Nasim S. Kadri

Krishnakant A. Pandat
B. Arch. A. I. I. A.,
Architect & Govt. Regd. Valuer
(Cha. Architect, Engineer & Govt. Regd. Valuer)
Regd. No. EA/38/11826
Govt. approved immo. Property valuer cat-I